News January 2026

Visit our website

Astemo
Mobility Beyond

Throttle Body

Hüco No. 139038 / Astemo No. 2509038




RENAULT	7701051585
RENAULT	8200065648
RENAULT	8200067219
RENAULT	8200166869
RENAULT	8200166870

Hüco No. 139039 / Astemo No. 2509039



FORD	1252882
FORD	1330253
FORD	4M5G9F991FA
VOLVO	30658190
VOLVO	31293045

Hüco No. 139041 / Astemo No. 2509041



OPEL	825243
VAUXHALL	825243
OPEL	9157512
VAUXHALL	9157512

Hüco No. 139042 / Astemo No. 2509042



VW GROUP	06A133062C
VW GROUP	06A133062BD

Hüco No. 139043 / Astemo No. 2509043



VW GROUP	059145950R
VW GROUP	059145950A
VW GROUP	059145950D
VW GROUP	059145950H

Hüco No. 139044 / Astemo No. 2509044



DACIA	161202859R
RENAULT	161202859R
DACIA	8200285017
DACIA	8200568712
RENAULT	8200568712

Hüco No. 139046 / Astemo No. 2509046



MERCEDES-BENZ	A1110980050
MERCEDES-BENZ	A1110980109
MERCEDES-BENZ	1110980050
MERCEDES-BENZ	1110980109

Astemo Aftermarket Germany GmbH
Eugen-Gerstenmaier-Str. 8 • 32339 Espelkamp • Germany
Tel: +49 (0) 5772 567 890
E-Mail: emea.af@astemo.com

News January 2026

Visit our website

Astemo
Mobility Beyond

EGR-Valve

Hüco No. 135954 / Astemo No. 2505954		
	NISSAN	1471000Q0K
	RENAULT	8200846454
	DACIA	8200846454

Hüco No. 135955 / Astemo No. 2505955		
	RENAULT	8200270177
	RENAULT	8200561269
	NISSAN	1471000Q0E
	NISSAN	1471000Q0G
	SUZUKI	1852084A53

Hüco No. 135956 / Astemo No. 2505956		
	VW GROUP	04L131501AD
	VW GROUP	04L131501F
	VW GROUP	04L131501R


Wheel speed sensor

Hüco No. 131395 / Astemo No. 2501395		
	LAND ROVER	SSB500133

Hüco No. 131396 / Astemo No. 2501396		
	LAND ROVER	LR072107
	LAND ROVER	LR062671

Hüco No. 131397 / Astemo No. 2501397		
	LAND ROVER	LR090859
	JAGUAR	LR090859
	JAGUAR	T4A2784
	LAND ROVER	T4A2784

Hüco No. 131398 / Astemo No. 2501398		
	JAGUAR	J8A29E731AA
	JAGUAR	J8A29E731AB
	JAGUAR	T4A12595
	LAND ROVER	LR140695
	LAND ROVER	LR090860



OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service.
If you would like to unsubscribe from the newsletter please let us know.

News January 2026

Visit our website

Astemo
Mobility Beyond

Wheel speed sensor

Hüco No. 131399 / Astemo No. 2501399



LAND ROVER	LR024203

Hüco No. 131671 / Astemo No. 2501671



LAND ROVER	LR039934
LAND ROVER	LR062647

Hüco No. 131672 / Astemo No. 2501672



LAND ROVER	CPLA2C190AB
LAND ROVER	LR033457

Hüco No. 131673 / Astemo No. 2501673



LAND ROVER	LR081609

Hüco No. 131674 / Astemo No. 2501674



LAND ROVER	LR082224
LAND ROVER	LR066868
LAND ROVER	LR024208

Hüco No. 131675 / Astemo No. 2501675



LAND ROVER	SSB500100
LAND ROVER	SSB500102

Hüco No. 131676 / Astemo No. 2501676



LAND ROVER	LR001056
LAND ROVER	6G9N2B372AB

Hüco No. 131677 / Astemo No. 2501677



LAND ROVER	LR013783
LAND ROVER	AH229E731AB

Hüco No. 131678 / Astemo No. 2501678



LAND ROVER	LR033461

Hüco No. 131679 / Astemo No. 2501679



LAND ROVER	LR081610
LAND ROVER	HPLA2C204BA

Astemo Aftermarket Germany GmbH
Eugen-Gerstenmaier-Str. 8 • 32339 Espelkamp • Germany
Tel: +49 (0) 5772 567 890
E-Mail: emea.af@astemo.com

News January 2026

Visit our website

Astemo
Mobility Beyond

Wheel speed sensor

Hüco No. 131680 / Astemo No. 2501680



CHEVROLET	95937220
CHEVROLET	95976062
LAND ROVER	LR024202
LAND ROVER	LR071974

Hüco No. 131681 / Astemo No. 2501681



LAND ROVER	SSB500092

Crankshaft position sensor

Hüco No. 131737 / Astemo No. 2501737



HONDA	37500RB0006

Hüco No. 131738 / Astemo No. 2501738



HONDA	37500PNA003
HONDA	37500PNB003

Sensor, camshaft position

Hüco No. 131781 / Astemo No. 2501781



LAND ROVER	LR013458

Hüco No. 131782 / Astemo No. 2501782



LAND ROVER	LR084884
LAND ROVER	LR079620
FORD	AS7Z6B288B
FORD	1947194
FORD	AS7112K073AA

Hüco No. 131783 / Astemo No. 2501783




FORD	6M8Z12K073AA
FORD	6M8Z6B288B
FORD	6M8Z6B288C
MAZDA	L3G118221
MAZDA	ZZCA18230A

Hüco No. 131784 / Astemo No. 2501784



CHEVROLET	55565709
GENERAL MOTORS	55565709
GENERAL MOTORS	25195556
OPEL	25195556
OPEL	6235752



OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service.
If you would like to unsubscribe from the newsletter please let us know.

News January 2026

Visit our website

Astemo
Mobility Beyond

Sensor, camshaft position

Hüco No. 131785 / Astemo No. 2501785



HYUNDAI	3935026900
KIA	3935026900

Hüco No. 131786 / Astemo No. 2501786



MAZDA	PE0118230

Hüco No. 131787 / Astemo No. 2501787



HONDA	37840PLC000
HONDA	37840PLC006
HONDA	37840RJH006
MITSUBISHI	J5T23991
MITSUBISHI	J5T23992

Hüco No. 131788 / Astemo No. 2501788

replaces 138071 / 2508071



HONDA	37510PNA003
HONDA	37510PNB003

Sealing / Protective cap (universal)

Hüco No. 133003 / Astemo No. 2503003



VW GROUP	8E0201263G

Hüco No. 133004 / Astemo No. 2503004



VW GROUP	8R0201263A

Check our YouTube Channel for new videos.

Visit us on YouTube

Astemo Aftermarket Germany GmbH
Eugen-Gerstenmaier-Str. 8 • 32339 Espelkamp • Germany
Tel: +49 (0) 5772 567 890
E-Mail: emea.af@astemo.com